

26 September 1958

Conference

STAT

Change angle speed of shutter to be decided  
present least speed is 1/50 second.

Can do 2 frames/second but to be decided.  
Sensor is 2 ma on stand-by.

Can hold shutter open  
Pulse operation only.

No knob for boresight 1/2 cycle

Same basic size of casting.

Additional optical trigger (building block) including sight (K-100 sensor)  
No solenoid.

Eymo mount out. Leica mounts for the 5 cameras. Probably can use 50 mm lens.

Plug-in amplifier. Is this necessary? In the shutter adjustment system!

No more total power drain.  
Numbering device will be incorporated.

STAT

Program arrangement. None.

to talk with  after his visit  next week.

STAT

(Pencil in conference of  and WSG)

STAT

STAT